

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	0.00	Rating **	A	Issue No.	10
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			39.194083° -121.935512°	39.194083° -121.935512°
DWR ID	DWR_ST0003_01_f_2016_10				
Comment Code					
Inspector Comment					
LMA has O+M manual.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	15
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			39.194083° -121.935512°	39.194083° -121.935512°
DWR ID	DWR_ST0003_01_f_2016_15				
Comment Code					
Inspector Comment					
LMA has a stockpile of supplies.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	16
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			39.194083° -121.935512°	39.194083° -121.935512°
DWR ID	DWR_ST0003_01_f_2016_16				
Comment Code					
Inspector Comment					
The LMA attends annual training and maintains emergency response plans.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Sutter Maintenance Yard East Levee Sacramento River

View of the erosion along the waterside slope.

No Photos

View of the ruts along the waterside slope.

Page 2 of 50

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	0.51	Rating **	A/W	Issue No.	137
LM End	0.51	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.197028 °	39.197028 °
				-121.943597 °	-121.943597 °
DWR ID	17307				
Comment Code					
Inspector Comment					
FS_ID:51650 DS_ID:17307 EP_NO: 9534 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 10/27/2017 This structure is inspected annually under the Structure and Channel Summer Inspection (part of the Levee Inspection Program) conducted by the DWR Flood Project Integrity and Inspection Branch (FPIIB). (DWR UCIP - O. Magana) 4/24/2017 Both sides of crossing were underwater during site visit. Will need to revisit after water levels drop. (DWR Sutter Yard-AFreitag) 11/7/2016 Crossing appears to be in good condition. (DWR Sutter Yard- AFreitag) 6/6/2016 Crossing appears to be in good condition. 4/6/2015 Good Condition. No issues. Semi circle CMP half riser in inlet structure on LS. Inlet opeing has no trash rack, this may cause safety issue. 6/30/2014 Same as last inspection. 12/30/2013 Same as last inspection. 7/29/2013 Same as last inspection. FIELD_STRUCT_DESC: [Butte Slough Drainage Structure] 78-inch drainage pipe of an unknown material through the levee, 3 feet below the crown. Flap gate on the waterside (WS). Corrugated metal pipe (CMP) half riser (in a semi-circle configuration) in the inlet structure on the landside (LS). (78-inch pipe [HLM 0.44] authorized under Automatic Board Order (ABO) issued as Permit No. 9534, 1974 - Caleta). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 0.44)]. FS Date: 4/26/2017 9:46:51 AM					

LM Start	0.51	Rating **	A/W	Issue No.	137 (cont)
LM End	0.51	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_51650_46962.jpg



Waterside view: overview towards CMP sewer pipe

Photo 2 of 3 : UCIP_FA_2018_51650_46960.jpg



Waterside view: water flowing from CMP sewer pipe

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	0.51	Rating **	A/W	Issue No.	137 (cont)	
LM End	0.51	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.197028 °	39.197028 °	
				-121.943597 °	-121.943597 °	
DWR ID	17307					
Comment Code						
Inspector Comment						
FS_ID:51650 DS_ID:17307 EP_NO: 9534 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 10/27/2017 This structure is inspected annually under the Structure and Channel Summer Inspection (part of the Levee Inspection Program) conducted by the DWR Flood Project Integrity and Inspection Branch (FPIIB). (DWR UCIP - O. Magana) 4/24/2017 Both sides of crossing were underwater during site visit. Will need to revisit after water levels drop. (DWR Sutter Yard-AFreitag)11/7/2016 Crossing appears to be in good condition. (DWR Sutter Yard- AFreitag)6/6/2016 Crossing appears to be in good condition.4/6/2015 Good Condition. No issues. Semi circle CMP half riser in inlet structure on LS. Inlet opeing has no trash rack, this may cause safety issue.6/30/2014 Same as last inspection.12/30/2013 Same as last inspection.7/29/2013 Same as last inspection. FIELD_STRUCT_DESC: [Butte Slough Drainage Structure] 78-inch drainage pipe of an unknown material through the levee, 3 feet below the crown. Flap gate on the waterside (WS). Corrugated metal pipe (CMP) half riser (in a semi-circle configuration) in the inlet structure on the landside (LS). (78-inch pipe [HLM 0.44] authorized under Automatic Board Order (ABO) issued as Permit No. 9534, 1974 - Caleta). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 0.44)]. FS Date: 4/26/2017 9:46:51 AM						

Photo 3 of 3 : UCIP_FA_2018_51650_46961.jpg



Landside view: overview

LM Start	0.54	Rating **	M	Issue No.	9
LM End	0.68	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.197267°	39.198178°
				-121.944232°	-121.946412°
DWR ID	DWR_ST0003_01_s_2017_9				
Comment Code					
DE : Debris					
Inspector Comment					
Remove the debris from the waterside slope.					

Photo 1 of 1 : FA_2018_ST0003_264_9_20180905_00007.jpg



View of the debris along the waterside slope.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	1.17	Rating **	M	Issue No.	80
LM End	1.17	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.194126°	39.194126°
				-121.953345°	-121.953345°
DWR ID	DWR_ST0003_01_f_2016_80				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					

Photo 1 of 1 : FA_2018_ST0003_264_80_20180905_00018.jpg



View of the slope instability along the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	1.44	Rating **	U	Issue No.	139
LM End	1.44	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		39.192502 °	39.192502 °	
			-121.958062 °	-121.958062 °	
DWR ID	17320				

Comment Code

Inspector Comment

FS_ID:53400
DS_ID:17320
EP_NO: 9543
Repair Type: Urgent
Crossing Status: Found
UCIP Comments: 8/30/2018 WS vegetation too thick to clearly inspect WS pipe so assume same condition as last inspections so crossing remains Urgent due to pipe integrity. WS levee slope looks good. No signs of levee threat to the road crown. LS headwall looks in good condition (D. Sanoski - DWR UCIP).4/24/2017 WS was underwater during the site visit but I do not believe that any repairs have been made to this crossing yet. (DWR Sutter Yard- AFreitag)11/7/2016 No repairs have been made here yet. (DWR Sutter Yard- AFreitag)6/17/2016 River levels were down and the WS pipe end was exposed. WS end is completely rotten and damaged and flap gate has fallen off the end of the pipe (see pics). Pipe needs to be replaced or repaired. (DWR Sutter Yard - afreitag)4/5/2016 Erosion on WS slope still present. Pipe still fully submerged on WS and discharging into river during site visit. (DWR UCIP - kfazel)4/6/2015 Pipe leaks during high water. DWR employee said he suspects that the flap gate has rotted and fallen off WS end of pipe. Could not locate WS end of pipe to confirm. Water was flowing through this drain during field survey. (DWR Sutter Yard - afreitag)6/30/2014 Same as last inspection. (DWR Sutter Yard - afreitag)12/30/2013 Same as last inspection. (DWR Sutter Yard - afreitag)7/29/2013 Same as last inspection. (DWR Sutter Yard - afreitag) 12/13/2012 Water was flowing through this drain during field survey. (DWR UCIP - pamatya)
FIELD_STRUCT_DESC: 30-inch corrugated metal drainage pipe (at 45 degrees) through the levee, 25.2 feet below the crown. Flap gate on the waterside (WS), not found in 2016. (30-inch pipe [HLM 1.38] authorized under Automatic Board Order (ABO) issued as Permit No. 9543, 1974 - Harada). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, revision March 1960 (HLM 1.38)]
FS Date: 8/30/2018 1:02:00 PM

Photo 1 of 3 : UCIP_FA_2018_53400_46992.jpg



Waterside view: overview of river bank

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	1.44	Rating **	U	Issue No.	139 (cont)
LM End	1.44	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.192502 °	39.192502 °
				-121.958062 °	-121.958062 °
DWR ID	17320				

Comment Code

Inspector Comment

FS_ID:53400
DS_ID:17320
EP_NO: 9543
Repair Type: Urgent
Crossing Status: Found
UCIP Comments: 8/30/2018 WS vegetation too thick to clearly inspect WS pipe so assume same condition as last inspections so crossing remains Urgent due to pipe integrity. WS levee slope looks good. No signs of levee threat to the road crown. LS headwall looks in good condition (D. Sanoski - DWR UCIP).4/24/2017 WS was underwater during the site visit but I do not believe that any repairs have been made to this crossing yet. (DWR Sutter Yard- A Freitag)11/7/2016 No repairs have been made here yet. (DWR Sutter Yard- A Freitag)6/17/2016 River levels were down and the WS pipe end was exposed. WS end is completely rotten and damaged and flap gate has fallen off the end of the pipe (see pics). Pipe needs to be replaced or repaired. (DWR Sutter Yard - a Freitag)4/5/2016 Erosion on WS slope still present. Pipe still fully submerged on WS and discharging into river during site visit. (DWR UCIP - kfazel)4/6/2015 Pipe leaks during high water. DWR employee said he suspects that the flap gate has rotted and fallen off WS end of pipe. Could not locate WS end of pipe to confirm. Water was flowing through this drain during field survey. (DWR Sutter Yard - a Freitag)6/30/2014 Same as last inspection. (DWR Sutter Yard - a Freitag)12/30/2013 Same as last inspection. (DWR Sutter Yard - a Freitag)7/29/2013 Same as last inspection. (DWR Sutter Yard - a Freitag) 12/13/2012 Water was flowing through this drain during field survey. (DWR UCIP - pamatya)
FIELD_STRUCT_DESC: 30-inch corrugated metal drainage pipe (at 45 degrees) through the levee, 25.2 feet below the crown. Flap gate on the waterside (WS), not found in 2016. (30-inch pipe [HLM 1.38] authorized under Automatic Board Order (ABO) issued as Permit No. 9543, 1974 - Harada). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, revision March 1960 (HLM 1.38)]
FS Date: 8/30/2018 1:02:00 PM

Photo 2 of 3 : UCIP_FA_2018_53400_46991.jpg



Waterside view: water flowing from outlet pipe (pipe fully submerge)

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

Sutter Maintenance Yard East Levee Sacramento River

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	2.45	Rating **	M	Issue No.	86
LM End	2.46	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.187911 °	39.187955 °
				-121.974591 °	-121.974693 °
DWR ID	DWR_ST0003_01_f_2016_86				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	2.56	Rating **	M	Issue No.	143	
LM End	2.56	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.188768 °	39.188768 °	
				-121.976305 °	-121.976305 °	
DWR ID	17309					
Comment Code						
Inspector Comment						
FS_ID:51660 DS_ID:17309 EP_NO: 9541 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 4/24/2017 Still no sign of WS pipe end or flapgate. LS appears to be in good condition. (DWR Sutter Yard- AFreitag) 11/7/2016 LS culvert measured to be 30"wide X 30"tall. WS end is not visible so could not be measured. (DWR Sutter Yard- AFreitag)6/6/2016 Cannot locate the WS headwall/flapgate. Appears to have been silted over.4/6/2015 Same as last inspection. Concrete surg box on WS. Flap gate in concrete "U" headwall at the waterward end- not found.6/30/2014 Same as last inspection.12/30/2013 Same as last inspection.7/29/2013 Same as last inspection. FIELD_STRUCT_DESC: 30-inch reinforced concrete box drainage culvert through the levee, 14.3 feet below the crown. 30-inch corrugated metal pipe connects concrete culvert from slide gate out to flap gate on the waterside (WS) end. Slide gate in a concrete riser on the waterside (WS) slope. (30-inch pipe [HLM 2.49] authorized under Automatic Board Order (ABO) issued as Permit No. 9541, 1974 - Wilbur, McGowan, Zinke). [Additional Reference(s): DWR Levee Logs, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 2.49)]. FS Date: 4/26/2017 10:46:22 AM						

Photo 1 of 3 : UCIP_FA_2018_51660_47027.jpg



Waterside view: overview- concrete surg tank

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	2.56	Rating **	M	Issue No.	143 (cont)
LM End	2.56	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.188768 °	39.188768 °
				-121.976305 °	-121.976305 °
DWR ID	17309				
Comment Code					
Inspector Comment					
FS_ID:51660 DS_ID:17309 EP_NO: 9541 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 4/24/2017 Still no sign of WS pipe end or flapgate. LS appears to be in good condition. (DWR Sutter Yard- AFreitag) 11/7/2016 LS culvert measured to be 30"wide X 30"tall. WS end is not vidible so could not be measured. (DWR Sutter Yard- AFreitag)6/6/2016 Cannot locate the WS headwall/flapgate. Appears to have been silted over.4/6/2015 Same as last inspection. Concrete surg box on WS. Flap gate in concrete "U" headwall at the waterward end- not found.6/30/2014 Same as last inspection.12/30/2013 Same as last inspection.7/29/2013 Same as last inspection. FIELD_STRUCT_DESC: 30-inch reinforced concrete box drainage culvert through the levee, 14.3 feet below the crown. 30-inch corrugated metal pipe connects concrete culvert from slide gate out to flap gate on the waterside (WS) end. Slide gate in a concrete riser on the waterside (WS) slope. (30-inch pipe [HLM 2.49] authorized under Automatic Board Order (ABO) issued as Permit No. 9541, 1974 - Wilbur, McGowan, Zinke). [Additional Reference(s): DWR Levee Logs, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 2.49)]. FS Date: 4/26/2017 10:46:22 AM					

LM Start	2.56	Rating **	M	Issue No.	143 (cont)
LM End	2.56	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_51660_47026.jpg



Waterside view: overview- concrete surg tank

Photo 3 of 3 : UCIP_FA_2018_51660_47025.jpg



Waterside view: slide gate inside concrete surg tank

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	2.84	Rating **	M	Issue No.	104
LM End	2.84	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.191162 °	39.191162 °
				-121.980365 °	-121.980365 °
DWR ID	DWR_ST0003_01_s_2018_104				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Repair the erosion along the water side slope caused by vehicle traffic.					

Photo 1 of 1 : FA_2018_ST0003_264_104_20180905_00024.jpg



View of the erosion along the waterside slope caused by vehicle traffic.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	3.32	Rating **	U	Issue No.	144 (cont)	
LM End	3.32	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.196865 °	39.196865 °	
				-121.985280 °	-121.985280 °	
DWR ID	17311					
Comment Code						
Inspector Comment						
FS_ID:52949 DS_ID:17311 EP_NO: N/A Repair Type: Urgent Crossing Status: Found UCIP Comments: 8/30/2018 Pipe found; at a different Lat/Long than is listed, however. Revised Lat/Long is (39.196865, -121.985280; CLM 3.32). WS pipe end is visible and has a functioning slide gate; LS pipe end is exposed with no closure device or headwall. Keeping as Urgent because the LS pipe discharges into a hole and could pose a threat to the levee prism during a high water event. There are also cracks on the crown that could be related to the pipe beneath. Recommend an internal pipe inspection to be sure of the levee integrity (D.Sanoski - DWR UCIP).4/6/2017 Pipe was found in January 2017 during a high water event when water uncovered the buried WS end which led to uncontrolled water flow through during the high water event. The WS pipe opening was temporarily blocked off by plywood and sandbags until the pipe can be properly plugged or abandoned. Pics updated. (DWR Sutter Yard- Afreitag)11/7/2016 Unable to locate. (DWR Sutter Yard- AFreitag)6/6/2016 Unable to locate.4/6/2015 Unable to locate.6/30/2014 Unable to locate.12/30/2013 Unable to locate.7/29/2013 Same as last inspection. Unable to locate. FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 12.4 feet below the crown. Slide gate on the waterside (WS) end. (Automatic Board Order (ABO) issued as Permit No. 9539, 1974 - Locvich). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 3.25)]. FS Date: 8/30/2018 1:45:35 PM						

Photo 2 of 3 : UCIP_FA_2018_52949_76920.jpg



LS view from levee shoulder

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Sutter Maintenance Yard East Levee Sacramento River

WS view of the temporary plug on WS end.

Page 14 of 50

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	3.68	Rating **	M	Issue No.	146
LM End	3.68	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.201831 °	39.201831 °
				-121.984006 °	-121.984006 °
DWR ID	17313				
Comment Code					
Inspector Comment					
FS_ID:51666 DS_ID:17313 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 4/24/2017 Slide gate structure found on WS about 10ft from levee toe. Vegetation was too thick to see if there were any more appurtances associated with this crossing visible on the WS. Nothing was visible on the LS. House located above pipe alignment at LS levee toe. Crossing appears abandoned and should be done so properly. (DWR Sutter Yard- A Freitag)11/7/2016 Unable to locate. (DWR Sutter Yard- A Freitag)6/6/2016 Unable to locate.4/6/2015 Unable to locate.6/30/2014 Unable to locate.12/30/2013 Unable to locate7/29/2013 Same as last inspection. Unable to locate. FIELD_STRUCT_DESC: *ABANDONED* 18-inch corrugated metal drainage pipe through the levee, 15 feet below the crown. Slide gate on the waterside (WS) end. [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 3.6)]. FS Date: 4/26/2017 12:11:41 PM					

LM Start	3.68	Rating **	M	Issue No.	146 (cont)
LM End	3.68	Issue Type +	Ma	Location *	

Photo 1 of 2 : UCIP_FA_2018_51666_77004.jpg



Slide gate structure found on WS

Photo 2 of 2 : UCIP_FA_2018_51666_77005.jpg



View of WS from levee shoulder

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Sutter Maintenance Yard East Levee Sacramento River

No Photos

View of the overgrown vegetation along the landside slope.

View of the downed tree along the landside slope.Page 16 of 50

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	6.75	Rating **	M	Issue No.	97
LM End	6.75	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.228291 °	39.228291 °
				-121.998579 °	-121.998579 °
DWR ID	DWR_ST0003_01_f_2016_97				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					

No Photos

LM Start	6.76	Rating **	M	Issue No.	136
LM End	6.79	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			39.228311 °	39.228730 °
				-121.998555 °	-121.998109 °
DWR ID	DWR_ST0003_01_f_2017_136				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:11					
Site Designation:DWR_ST0003_01_s_2012_30					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:6/7/2017					
Notes: Rodent activity seems to be the source of the problem. Local runoff/rainfall eroded the rodent holes to an advanced state of erosion that could continue with future exposure to wet conditions. Simple fix for the issue would be to grout the holes. Problem levee is a set-back levee.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	7.72	Rating **	M	Issue No.	160
LM End	7.72	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		39.239458°	39.239458°	
			-121.993398°	-121.993398°	
DWR ID	17301				

Comment Code

Inspector Comment

FS_ID:51695
DS_ID:17301
EP_NO: 9532
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: 4/19/2017 Abandoned- erosion/depression present around the WS box (DWR Sutter Yard- AFreitag)10/31/2016 Abandoned and erosion still present near WS box.(DWR Sutter Yard- AFreitag)6/1/2016 Appears to be an abandoned crossing.4/1/2015 Silted concrete box on WS. Depression/erosion around concrete box on WS.Silted concrete box on WS. Depression/erosion around concrete box on WS.6/30/2014 Same as last inspection.12/18/2013 Same as last inspection.7/23/2013 Same as last inspection.
FIELD_STRUCT_DESC: *ABANDONED* 36-inch by 48-inch reinforced concrete box drainage culvert through the levee, 11.6 feet below the crown. Slide gate in a concrete box on the waterside (WS) slope. (3-foot by 4-foot culvert [HLM 7.73] authorized under Automatic Board Order (ABO) issued as Permit No. 9532, 1974 - Martin). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 7.73)].
FS Date: 4/26/2017 2:38:29 PM

LM Start	7.72	Rating **	M	Issue No.	160 (cont)
LM End	7.72	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_51695_77008.jpg



Depression around WS concrete box

Photo 2 of 3 : UCIP_FA_2018_51695_77009.jpg



depression around WS concrete box

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	7.72	Rating **	M	Issue No.	160 (cont)	
LM End	7.72	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.239458 °	39.239458 °	
				-121.993398 °	-121.993398 °	
DWR ID	17301					
Comment Code						
Inspector Comment						
FS_ID:51695 DS_ID:17301 EP_NO: 9532 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 4/19/2017 Abandoned- erosion/depression present around the WS box (DWR Sutter Yard- AFreitag)10/31/2016 Abandoned and erosion still present near WS box.(DWR Sutter Yard-AFreitag)6/1/2016 Appears to be an abandoned crossing.4/1/2015 Silted concrete box on WS. Depression/erosion around concrete box on WS.Silted concrete box on WS. Depression/erosion around concrete box on WS.6/30/2014 Same as last inspection.12/18/2013 Same as last inspection.7/23/2013 Same as last inspection. FIELD_STRUCT_DESC: *ABANDONED* 36-inch by 48-inch reinforced concrete box drainage culvert through the levee, 11.6 feet below the crown. Slide gate in a concrete box on the waterside (WS) slope. (3-foot by 4-foot culvert [HLM 7.73] authorized under Automatic Board Order (ABO) issued as Permit No. 9532, 1974 - Martin). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 7.73)]. FS Date: 4/26/2017 2:38:29 PM						

Photo 3 of 3 : UCIP_FA_2018_51695_77010.jpg



WS concrete box full of silt.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	8.32	Rating **	M	Issue No.	161
LM End	8.32	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.246317 °	39.246317 °
				-121.998825 °	-121.998825 °
DWR ID	17304				
Comment Code					
Inspector Comment					
FS_ID:51698 DS_ID:17304 EP_NO: 9529 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 4/19/2017 Abandoned- needs to be done properly. (DWR Sutter Yard- AFreitag)10/31/2016 Abandoned (DWR Sutter Yard- Afreitag)6/1/2016 Abandoned- only WS riser and slide gate found.4/1/2015 CMP riser and slide gate on WS. LS distribution box is silted in. Looks abandoned. CMP riser with slide gate on WS. Concrete distribution box on LS- full with silt.6/30/2014 Same as last inspection.12/18/2013 Same as last inspection.7/23/2013 Same as last inspection. FIELD_STRUCT_DESC: *ABANDONED* 24-inch corrugated metal drainage pipe through the levee, invert 12.8 feet below the crown. Slide gate in a corrugated metal pipe (CMP) riser on the waterside (WS) slope. Concrete box at the landside (LS) toe. (24-inch pipe [HLM 8.35] authorized under Automatic Board Order (ABO) issued as Permit No. 9529, 1974 - Dorwood Ranching Company). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 8.35)]. FS Date: 4/26/2017 2:54:54 PM					

LM Start	8.32	Rating **	M	Issue No.	161 (cont)
LM End	8.32	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_51698_47202.jpg



Crown view: overview (both sides of the levee)

Photo 2 of 3 : UCIP_FA_2018_51698_47201.jpg



Waterside view: overview of CMP riser

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	8.32	Rating **	M	Issue No.	161 (cont)	
LM End	8.32	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			39.246317 °		39.246317 °
				-121.998825 °		-121.998825 °
DWR ID	17304					
Comment Code						
Inspector Comment						
FS_ID:51698 DS_ID:17304 EP_NO: 9529 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 4/19/2017 Abandoned- needs to be done properly. (DWR Sutter Yard- AFreitag)10/31/2016 Abandoned (DWR Sutter Yard- AFreitag)6/1/2016 Abandoned- only WS riser and slide gate found.4/1/2015 CMP riser and slide gate on WS. LS distribution box is silted in. Looks abandoned. CMP riser with slide gate on WS. Concrete distribution box on LS- full with silt.6/30/2014 Same as last inspection.12/18/2013 Same as last inspection.7/23/2013 Same as last inspection. FIELD_STRUCT_DESC: *ABANDONED* 24-inch corrugated metal drainage pipe through the levee, invert 12.8 feet below the crown. Slide gate in a corrugated metal pipe (CMP) riser on the waterside (WS) slope. Concrete box at the landside (LS) toe. (24-inch pipe [HLM 8.35] authorized under Automatic Board Order (ABO) issued as Permit No. 9529, 1974 - Dorwood Ranching Company). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 8.35)]. FS Date: 4/26/2017 2:54:54 PM						

Photo 3 of 3 : UCIP_FA_2018_51698_47200.jpg



Landside view: overview of concrete box

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	8.52	Rating **	A/W	Issue No.	163
LM End	8.52	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.249125°	39.249125°
				-121.999031°	-121.999031°
DWR ID	17295				

Comment Code

Inspector Comment

FS_ID:51725
DS_ID:17295
EP_NO: 9529
Repair Type: No Action Needed
Crossing Status: Found
UCIP Comments: 09/21/2017 Permit review indicates this 24-inch pipe was authorized as an irrigation and drainage pipe under ABO issued as Permit No. 9529, structure description was updated. Structure type logged as drainage. (DWR UCIP - O. Magana)
4/19/2017 Abandoned- needs to be done so properly. (DWR Sutter Yard- Afreitag)10/31/2016 Abandoned. (DWR Sutter Yard- Afreitag)6/13/2016 Pipe was exposed and camera inspected by Nor-Cal Pipeline Services 10/29/2015. Photos of the exposed pipe ends were uploaded on 4/1/2015. The internal inspection showed some signs of rust but no visible holes or deterioration were found. After the inspection the pipe ends were capped and reburied.6/9/2016 Khalida Fazel of UCIP requests that any photos of the pipe when it was exposed for a video inspection be kindly uploaded here.4/4/2016 Proper abandonment of pipe is needed. Pipe has been buried again after it was dug up and video inspected, so was not visible on LS. Note that landowner has regraded LS slope so drainage is now to the east (toward LS).4/1/2015 Both WS and LS pipe ends have been dug up in preparation for an internal camera inspection. Pipe shows signs of heavy rust and both ends of pipe are plugged with soil.Only a CMP riser with slide gate found on WS.6/30/2014 Same as last inspection.12/18/2013 Same as last inspection.7/23/2013 Same as last inspection.
FIELD_STRUCT_DESC: *ABANDONED* 24-inch irrigation and drainage pipe through the levee, invert 11.5 feet below the crown. Slide gate in a corrugated metal pipe (CMP) riser on the waterside (WS) slope. (24-inch pipe [HLM 8.55] authorized under Automatic Board Order (ABO) issued as Permit No. 9529, 1974 - Dorwood Ranching Co.) [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 8.55)]
FS Date: 5/1/2017 8:37:22 AM

Photo 1 of 3 : UCIP_FA_2018_51725_47208.jpg



Waterside view: overview of CMP riser

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	8.52	Rating **	A/W	Issue No.	163 (cont)	
LM End	8.52	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.249125 °	39.249125 °	
				-121.999031 °	-121.999031 °	
DWR ID	17295					

Comment Code

Inspector Comment

FS_ID:51725

DS_ID:17295

EP_NO: 9529

Repair Type: No Action Needed

Crossing Status: Found

UCIP Comments: 09/21/2017 Permit review indicates this 24-inch pipe was authorized as an irrigation and drainage pipe under ABO issued as Permit No. 9529, structure description was updated. Structure type logged as drainage. (DWR UCIP - O. Magana)

4/19/2017 Abandoned- needs to be done so properly. (DWR Sutter Yard- Afreitag)10/31/2016 Abandoned. (DWR Sutter Yard- Afreitag)6/13/2016 Pipe was exposed and camera inspected by Nor-Cal Pipeline Services 10/29/2015. Photos of the exposed pipe ends were uploaded on 4/1/2015. The internal inspection showed some signs of rust but no visible holes or deterioration were found. After the inspection the pipe ends were capped and reburied.6/9/2016 Khalida Fazel of UCIP requests that any photos of the pipe when it was exposed for a video inspection be kindly uploaded here.4/4/2016 Proper abandonment of pipe is needed. Pipe has been buried again after it was dug up and video inspected, so was not visible on LS. Note that landowner has regraded LS slope so drainage is now to the east (toward LS).4/1/2015 Both WS and LS pipe ends have been dug up in preparation for an internal camera inspection. Pipe shows signs of heavy rust and both ends of pipe are plugged with soil.Only a CMP riser with slide gate found on WS.6/30/2014 Same as last inspection.12/18/2013 Same as last inspection.7/23/2013 Same as last inspection.

FIELD_STRUCT_DESC: *ABANDONED* 24-inch irrigation and drainage pipe through the levee, invert 11.5 feet below the crown. Slide gate in a corrugated metal pipe (CMP) riser on the waterside (WS) slope. (24-inch pipe [HLM 8.55] authorized under Automatic Board Order (ABO) issued as Permit No. 9529, 1974 - Dorwood Ranching Co.) [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 8.55)]

FS Date: 5/1/2017 8:37:22 AM

Photo 2 of 3 : UCIP_FA_2018_51725_47207.jpg



Landside view: overview (no pipes)

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	8.52	Rating **	A/W	Issue No.	163 (cont)	
LM End	8.52	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.249125 °	39.249125 °	
				-121.999031 °	-121.999031 °	
DWR ID	17295					

Comment Code

Inspector Comment

FS_ID:51725

DS_ID:17295

EP_NO: 9529

Repair Type: No Action Needed

Crossing Status: Found

UCIP Comments: 09/21/2017 Permit review indicates this 24-inch pipe was authorized as an irrigation and drainage pipe under ABO issued as Permit No. 9529, structure description was updated. Structure type logged as drainage. (DWR UCIP - O. Magana)

4/19/2017 Abandoned- needs to be done so properly. (DWR Sutter Yard- Afreitag)10/31/2016 Abandoned. (DWR Sutter Yard- Afreitag)6/13/2016 Pipe was exposed and camera inspected by Nor-Cal Pipeline Services 10/29/2015. Photos of the exposed pipe ends were uploaded on 4/1/2015. The internal inspection showed some signs of rust but no visible holes or deterioration were found. After the inspection the pipe ends were capped and reburied.6/9/2016 Khalida Fazel of UCIP requests that any photos of the pipe when it was exposed for a video inspection be kindly uploaded here.4/4/2016 Proper abandonment of pipe is needed. Pipe has been buried again after it was dug up and video inspected, so was not visible on LS. Note that landowner has regraded LS slope so drainage is now to the east (toward LS).4/1/2015 Both WS and LS pipe ends have been dug up in preparation for an internal camera inspection. Pipe shows signs of heavy rust and both ends of pipe are plugged with soil.Only a CMP riser with slide gate found on WS.6/30/2014 Same as last inspection.12/18/2013 Same as last inspection.7/23/2013 Same as last inspection.

FIELD_STRUCT_DESC: *ABANDONED* 24-inch irrigation and drainage pipe through the levee, invert 11.5 feet below the crown. Slide gate in a corrugated metal pipe (CMP) riser on the waterside (WS) slope. (24-inch pipe [HLM 8.55] authorized under Automatic Board Order (ABO) issued as Permit No. 9529, 1974 - Dorwood Ranching Co.) [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 8.55)]

FS Date: 5/1/2017 8:37:22 AM

Photo 3 of 3 : UCIP_FA_2018_51725_73640.jpg



WS pipe end

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	8.56	Rating **	M	Issue No.	164
LM End	8.56	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.249678 °	39.249678 °
				-121.999021 °	-121.999021 °
DWR ID	17327				

Comment Code

Inspector Comment

FS_ID:51726
DS_ID:17327
EP_NO: 9528
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: 4/19/2017 Abandoned- needs to be done so properly. (DWR Sutter Yard- Afreitag)10/31/2016 Abandoned. (DWR Sutter Yard- Afreitag)6/13/2016 Pipe was internally cleaned and camera inspected by Nor-Cal Pipeline Services on 10/29/2015. Pipe length through levee is 75.1ft long. The inspection showed some signs of rust but no holes or other deterioration were found. Pics of exposed pipe ends were uploaded on 4/1/2015. After the inspection the pipe ends were capped and reburied.4/14/2016- Same as last inspection.4/1/2015- Both ends of pipe have been dug up in preparation for internal camera inspections. Pipe shows some rust but appears to be in decent shape. Only buried slide gate structure found.6/30/2014- Same as last inspection.12/18/2013 Same as last inspection.7/23/2013 Same as last inspection.
FIELD_STRUCT_DESC: *ABANDONED* 24-inch corrugated metal drainage pipe through the levee, 12.5 feet below the crown. Slide gate on the waterside (WS). (Automatic Board Order (ABO) issued as Permit No. 9528, 1974 - Lamb). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 8.59)].
FS Date: 5/1/2017 8:51:02 AM

LM Start	8.56	Rating **	M	Issue No.	164 (cont)
LM End	8.56	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_51726_47210.jpg



Waterside view: overview

Photo 2 of 3 : UCIP_FA_2018_51726_47209.jpg



Waterside view: buried slide gate

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	8.56	Rating **	M	Issue No.	164 (cont)
LM End	8.56	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		39.249678 °	39.249678 °	
			-121.999021 °	-121.999021 °	
DWR ID	17327				
Comment Code					
Inspector Comment					
FS_ID:51726 DS_ID:17327 EP_NO: 9528 Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 4/19/2017 Abandoned- needs to be done so properly. (DWR Sutter Yard- Afreitag)10/31/2016 Abandoned. (DWR Sutter Yard- Afreitag)6/13/2016 Pipe was internally cleaned and camera inspected by Nor-Cal Pipeline Services on 10/29/2015. Pipe length through levee is 75.1ft long. The inspection showed some signs of rust but no holes or other deterioration were found. Pics of exposed pipe ends were uploaded on 4/1/2015. After the inspection the pipe ends were capped and reburied.4/14/2016- Same as last inspection.4/1/2015- Both ends of pipe have been dug up in preparation for internal camera inspections. Pipe shows some rust but appears to be in decent shape. Only buried slide gate structure found.6/30/2014- Same as last inspection.12/18/2013 Same as last inspection.7/23/2013 Same as last inspection. FIELD_STRUCT_DESC: *ABANDONED* 24-inch corrugated metal drainage pipe through the levee, 12.5 feet below the crown. Slide gate on the waterside (WS). (Automatic Board Order (ABO) issued as Permit No. 9528, 1974 - Lamb). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 8.59)]. FS Date: 5/1/2017 8:51:02 AM					

Photo 3 of 3 : UCIP_FA_2018_51726_73649.jpg



WS pipe end

LM Start	8.65	Rating **	M	Issue No.	94
LM End	8.65	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		39.250774 °	39.250774 °	
			-121.998242 °	-121.998242 °	
DWR ID	DWR_ST0003_01_f_2016_94				
Comment Code					
TR : Tree or limb					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	8.92	Rating **	N	Issue No.	92
LM End	8.92	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.254563°	39.254563°
				-121.997493°	-121.997493°
DWR ID	DWR_ST0003_01_f_2016_92				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

LM Start	9.03	Rating **	N	Issue No.	91
LM End	9.03	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.256141°	39.256141°
				-121.997785°	-121.997785°
DWR ID	DWR_ST0003_01_f_2016_91				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

LM Start	9.17	Rating **	N	Issue No.	90
LM End	9.17	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.257688°	39.257688°
				-121.999331°	-121.999331°
DWR ID	DWR_ST0003_01_f_2016_90				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	9.37	Rating **	A/W	Issue No.	167	
LM End	9.37	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.260034 °	39.260034 °	
				-122.000970 °	-122.000970 °	
DWR ID	17355					
Comment Code						
Inspector Comment						
FS_ID:51731						
DS_ID:17355						
EP_NO: N/A						
Repair Type: No Action Needed						
Crossing Status: Found						
UCIP Comments: 4/19/2017 Abandoned- needs to be done so properly. (DWR Sutter Yard- Afreitag)10/31/2016 Abandoned. (DWR Sutter Yard- Afreitag)6/13/2016 Pipe was internally cleaned and camera inspected on 10/30/2015 by Nor-Cal Pipeline Services. WS cap was removed and 100.6ft of pipe were inspected starting from the WS opening. Inspection revealed rusting but no visible holes or other deterioration were found. Pipe was recapped after the inspection. This pipe is always visible so no new photos were taken during the inspection.6/9/2016 Khalida Fazel of UCIP requests that any photos of the pipe when it was exposed for a video inspection be kindly uploaded here.4/1/2015 Pipe is in same condition. It has been selected for an internal camera inspection. New CMP pipe on WS capped with steel plate.6/30/2014 Same as last inspection.12/18/2013 Same as last inspection.7/23/2013 Same as last inspection.						
FIELD_STRUCT_DESC: *ABANDONED* 24-inch corrugated metal drainage pipe through the levee, 13.5 feet below the crown. Slide gate on the landside (LS) headwall. Steel plate welded on the waterside (WS) end. [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 9.4)].						
FS Date: 5/1/2017 9:16:26 AM						

LM Start	9.37	Rating **	A/W	Issue No.	167 (cont)
LM End	9.37	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_51731_47242.jpg



Waterside view: overview

Photo 2 of 3 : UCIP_FA_2018_51731_47241.jpg



Waterside view: overview of CMP pipe

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	9.37	Rating **	A/W	Issue No.	167 (cont)	
LM End	9.37	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.260034 °	39.260034 °	
				-122.000970 °	-122.000970 °	
DWR ID	17355					
Comment Code						
Inspector Comment						
FS_ID:51731 DS_ID:17355 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 4/19/2017 Abandoned- needs to be done so properly. (DWR Sutter Yard- Afreitag)10/31/2016 Abandoned. (DWR Sutter Yard- Afreitag)6/13/2016 Pipe was internally cleaned and camera inspected on 10/30/2015 by Nor-Cal Pipeline Services. WS cap was removed and 100.6ft of pipe were inspected starting from the WS opening. Inspection revealed rusting but no visible holes or other deterioration were found. Pipe was recapped after the inspection. This pipe is always visible so no new photos were taken during the inspection.6/9/2016 Khalida Fazel of UCIP requests that any photos of the pipe when it was exposed for a video inspection be kindly uploaded here.4/1/2015 Pipe is in same condition. It has been selected for an internal camera inspection. New CMP pipe on WS capped with steel plate.6/30/2014 Same as last inspection.12/18/2013 Same as last inspection.7/23/2013 Same as last inspection. FIELD_STRUCT_DESC: *ABANDONED* 24-inch corrugated metal drainage pipe through the levee, 13.5 feet below the crown. Slide gate on the landside (LS) headwall. Steel plate welded on the waterside (WS) end. [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 9.4)]. FS Date: 5/1/2017 9:16:26 AM						

Photo 3 of 3 : UCIP_FA_2018_51731_47240.jpg



Waterside view: capped CMP pipe

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	10.32	Rating **	M	Issue No.	1
LM End	10.41	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			39.331447 °	39.332716 °
				-122.029440 °	-122.029953 °
DWR ID	DWR_ST0003_01_f_2018_1				
Comment Code					
Inspector Comment					
2017 Site ID: SAC 157.7 R					
Status: Eroding					
2017 Field Notes: Vertical face of clay sand bank, new tree popout.					
Bank continues to erode.					
Site History: 2004 - Slowly eroding but near vertical with no vegetation to hold it. 2005 - Erosion is close to levee toe but not into the levee section yet. 2010 - Some new toe scour.					

Photo 1 of 1 : FA_2018_ST0003_264_1_20180905_00001.jpg



USACE 2013 Photo #1

LM Start	10.35	Rating **	A/W	Issue No.	168
LM End	10.35	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.270492 °	39.270492 °
				-122.001306 °	-122.001306 °
DWR ID	17358				
Comment Code					
Inspector Comment					
FS_ID:51734 DS_ID:17358 EP_NO: 9517 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 4/19/2017 No WS end found/ slide gate handle broken. (DWR Sutter Yard- Afreitag)10/31/2016 Slide gate handle is broken and no WS pipe end can be located. (DWR Sutter Yard-Afreitag)6/1/2016 WS slide gate handle is still broken. No WS pipe end was found.4/1/2015 Slide gate handle is still broken. The rest of the pipe appears in good condition. Broken slide gate handle found on WS.6/30/2014 Same as last inspection.12/18/2013 Same as last inspection.7/23/2013 Same as last inspection. FIELD_STRUCT_DESC: 48-inch corrugated metal drainage pipe through the levee, 14 feet below the crown. Slide gate in a 60-inch corrugated metal pipe (CMP) riser on the waterside (WS) slope. Slide gate in a concrete distribution box on the landside (LS) toe. (48-inch pipe [HLM 10.39] authorized under Automatic Board Order (ABO) issued as Permit No. 9517, 1974 - Griffin). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 10.47)]. FS Date: 5/1/2017 9:32:45 AM					

Photo 1 of 3 : UCIP_FA_2018_51734_47263.jpg



Crown view: overview (both sides of the levee)

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	10.35	Rating **	A/W	Issue No.	168 (cont)	
LM End	10.35	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.270492 °	39.270492 °	
				-122.001306 °	-122.001306 °	
DWR ID	17358					
Comment Code						
Inspector Comment						
FS_ID:51734 DS_ID:17358 EP_NO: 9517 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 4/19/2017 No WS end found/ slide gate handle broken. (DWR Sutter Yard- Afreitag)10/31/2016 Slide gate handle is broken and no WS pipe end can be located. (DWR Sutter Yard- Afreitag)6/1/2016 WS slide gate handle is still broken. No WS pipe end was found.4/1/2015 Slide gate handle is still broken. The rest of the pipe appears in good condition. Broken slide gate handle found on WS.6/30/2014 Same as last inspection.12/18/2013 Same as last inspection.7/23/2013 Same as last inspection. FIELD_STRUCT_DESC: 48-inch corrugated metal drainage pipe through the levee, 14 feet below the crown. Slide gate in a 60-inch corrugated metal pipe (CMP) riser on the waterside (WS) slope. Slide gate in a concrete distribution box on the landside (LS) toe. (48-inch pipe [HLM 10.39] authorized under Automatic Board Order (ABO) issued as Permit No. 9517, 1974 - Griffin). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 10.47)]. FS Date: 5/1/2017 9:32:45 AM						

LM Start	10.35	Rating **	A/W	Issue No.	168 (cont)
LM End	10.35	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_51734_47262.jpg



Waterside view: overview of CMP riser

Photo 3 of 3 : UCIP_FA_2018_51734_47268.jpg



Waterside view: inside CMP riser

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	10.36	Rating **	M	Issue No.	5
LM End	10.36	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.270503 °	39.270503 °
				-122.001339 °	-122.001339 °
DWR ID	DWR_ST0003_01_s_2012_5				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
The Elderberry is partially blocking visibility.					

No Photos

LM Start	11.53	Rating **	M	Issue No.	8
LM End	11.79	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			39.279910°	39.283853°
				-122.018221°	-122.016113°
DWR ID	DWR_ST0003_01_f_2018_8				
Comment Code					
Inspector Comment					
2017 Site ID: SAC 152.6 L					
Status: Eroding					
2017 Field Notes: Access Issues - Could not observe					
Site History: 2008 - Large rotational/mass failure in the bank with tree slump. 2009 - Minimal new erosion, the tree is leaning further into the river. 2011 - Site extended downstream. 2012 - Minor new erosion and tree roots are further exposed.					

Photo 1 of 1 : FA_2018_ST0003_264_8_20180905_00006.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	11.85	Rating **	M	Issue No.	13
LM End	11.90	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			39.284568 °	39.285298 °
				-122.015690 °	-122.015208 °
DWR ID	DWR_ST0003_01_f_2018_13				
Comment Code					
Inspector Comment					
2017 Site ID: SAC 152.8 L					
Status: Eroding					
2017 Field Notes: Minor new erosion observed.					
Site History: 2006 - Large rotational/mass failure in the bank with tree slump. Tough clayey toe material. 2007 - Site is between stone revetments with a pump station at the downstream end. 2010 - Erosion is into the levee toe. 2011 - Minor new erosion. 2012 - Minor new erosion.					

Photo 1 of 1 : FA_2018_ST0003_264_13_20180905_00010.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	13.38	Rating **	M	Issue No.	176
LM End	13.38	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.306065 °	39.306065 °
				-122.013112 °	-122.013112 °
DWR ID	17340				

Comment Code

Inspector Comment

FS_ID:51749

DS_ID:17340

EP_NO: 9511

Repair Type: Non-Urgent

Crossing Status: Found

UCIP Comments: 4/20/2017 Abandoned- needs to be done properly. A oak tree has fallen down onto the WS pipe end. It does not appear to have damaged the pipe but it will need to be better inspected after the tree has been cleared away. (DWR Sutter Yard- AFreitag)10/31/2016 Abandoned. (DWR Sutter Yard- AFreitag)6/14/2016 Pipe was internally cleaned and camera inspected on 11/6/2015 by Nor-Cal Pipeline Services. The 48" cmp pipe section that runs through the levee was deemed to be in good condition. After the LS levee toe the pipe changes to a 48" concrete box culvert for under the roadway and that showed signs of some cracking. After the inspection the WS end was capped to keep sediment out until further abandonment can be achieved.4/16/2016 A wooden board has been placed on WS outlet of pipe to prevent sediment from entering pipe. This is a temporary repair measure by Sutter Yard until pipe can be grouted. Need to contact owner to ensure pipe's proper abandonment. Blockage of pipe outlet by wooden board or sediment will pose a hazard during high water. Pipe owner unclear, as landowner differs on LS and WS.4/2/2015 Pipe has been selected for internal camera inspection.Outlet pipe silted on WS. Inlet structure damaged on LS. Not properly abandoned.7/2/2014 Same as last inspection.12/19/2013 Same as last inspection.7/23/2013 Same as last inspection.

FIELD_STRUCT_DESC: *ABANDONED* 48-inch corrugated metal drainage pipe through the levee, 16.5 feet below the crown. Slide gate in a 60-inch corrugated metal pipe (CMP) riser on the waterside (WS) slope. Landside (LS) end of pipe on east side of River Road. Pipe is not in use but is operable. (48-inch pipe [HLM 13.37] authorized under Permit No. 9511, 1974 - Moresco). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 13.37)].

FS Date: 5/1/2017 10:27:34 AM

Photo 1 of 3 : UCIP_FA_2018_51749_47343.jpg



Waterside view: CMP riser with slide gate

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	13.38	Rating **	M	Issue No.	176 (cont)
LM End	13.38	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		39.306065°	39.306065°	
			-122.013112°	-122.013112°	
DWR ID	17340				

Comment Code

Inspector Comment

FS_ID:51749
DS_ID:17340
EP_NO: 9511
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: 4/20/2017 Abandoned- needs to be done properly. A oak tree has fallen down onto the WS pipe end. It does not appear to have damaged the pipe but it will need to be better inspected after the tree has been cleared away. (DWR Sutter Yard- AFreitag)10/31/2016 Abandoned. (DWR Sutter Yard- AFreitag)6/14/2016 Pipe was internally cleaned and camera inspected on 11/6/2015 by Nor-Cal Pipeline Services. The 48" cmp pipe section that runs through the levee was deemed to be in good condition. After the LS levee toe the pipe changes to a 48" concrete box culvert for under the roadway and that showed signs of some cracking. After the inspection the WS end was capped to keep sediment out until further abandonment can be achieved.4/16/2016 A wooden board has been placed on WS outlet of pipe to prevent sediment from entering pipe. This is a temporary repair measure by Sutter Yard until pipe can be grouted. Need to contact owner to ensure pipe's proper abandonment. Blockage of pipe outlet by wooden board or sediment will pose a hazard during high water. Pipe owner unclear, as landowner differs on LS and WS.4/2/2015 Pipe has been selected for internal camera inspection.Outlet pipe silted on WS. Inlet structure damaged on LS. Not properly abandoned.7/2/2014 Same as last inspection.12/19/2013 Same as last inspection.7/23/2013 Same as last inspection.
FIELD_STRUCT_DESC: *ABANDONED* 48-inch corrugated metal drainage pipe through the levee, 16.5 feet below the crown. Slide gate in a 60-inch corrugated metal pipe (CMP) riser on the waterside (WS) slope. Landside (LS) end of pipe on east side of River Road. Pipe is not in use but is operable. (48-inch pipe [HLM 13.37] authorized under Permit No. 9511, 1974 - Moresco). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 13.37)].
FS Date: 5/1/2017 10:27:34 AM

Photo 2 of 3 : UCIP_FA_2018_51749_47342.jpg



Waterside view: overview of CMP riser and outlet pipe

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

Sutter Maintenance Yard East Levee Sacramento River

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable	A : Acceptable N : Not Inspected/Rated	Ma : Maintenance Deficiency
WS : Water Side	M : Minimally Acceptable C : Corrected	Ob : Design & System Obsolescence
CR : Crown	U : Unacceptable A/W : Acceptable but Monitor & Maintain	En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	13.43	Rating **	M	Issue No.	75
LM End	13.43	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.306919 °	39.306919 °
				-122.013076 °	-122.013076 °
DWR ID	DWR_ST0003_01_f_2016_75				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : FA_2018_ST0003_264_75_20180905_00016.jpg



View of the slope instability along the waterside slope.

LM Start	14.50	Rating **	A/W	Issue No.	178
LM End	14.50	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.321429 °	39.321429 °
				-122.016079 °	-122.016079 °
DWR ID	17330				
Comment Code					
Inspector Comment					
FS_ID:51752 DS_ID:17330 EP_NO: 9508 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 4/20/2017 Abandoned- needs to be done so properly. (DWR Sutter Yard- AFreitag)10/31/2016 Appears abandoned. WS pipe end buried. (DWR Sutter Yard- AFreitag)6/14/2016 Pipe was internally cleaned and camera inspected on 11/17/2015 by Nor-Cal Pipeline Services. Pipe section through levee is 86ft long and showed some signs of rusting but no visible holes or other deterioration was found. After the inspection the WS end was capped and reburied until further abandonment can be achieved.4/14/2016 Concrete box on LS cleared of sediment.4/2/2015 Same as last inspection. Concrete box on LS silted in. If abandoned it should be done so properly.7/2/2014 Same as last inspection.12/19/2013 Same as last inspection.7/23/2013 Same as last inspection. FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 14 feet below the crown. Slide gate in a 36-inch corrugated metal pipe (CMP) riser on the waterside (WS) slope. Concrete distribution box on the landside (LS). (24-inch pipe [HLM 14.5] authorized under Automatic Board Order (ABO) issued as Permit No. 9508, 1974 - Jones). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 14.5)]. FS Date: 5/1/2017 10:34:48 AM					

Photo 1 of 3 : UCIP_FA_2018_51752_47356.jpg



Waterside view: CMP riser with slide gate

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	14.50	Rating **	A/W	Issue No.	178 (cont)
LM End	14.50	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		39.321429°	39.321429°	
			-122.016079°	-122.016079°	
DWR ID	17330				

Comment Code

Inspector Comment

FS_ID:51752
DS_ID:17330
EP_NO: 9508
Repair Type: No Action Needed
Crossing Status: Found
UCIP Comments: 4/20/2017 Abandoned- needs to be done so properly. (DWR Sutter Yard- A Freitag)10/31/2016 Appears abandoned. WS pipe end buried. (DWR Sutter Yard- A Freitag)6/14/2016 Pipe was internally cleaned and camera inspected on 11/17/2015 by Nor-Cal Pipeline Services. Pipe section through levee is 86ft long and showed some signs of rusting but no visible holes or other deterioration was found. After the inspection the WS end was capped and reburied until further abandonment can be achieved.4/14/2016 Concrete box on LS cleared of sediment.4/2/2015 Same as last inspection. Concrete box on LS silted in. If abandoned it should be done so properly.7/2/2014 Same as last inspection.12/19/2013 Same as last inspection.7/23/2013 Same as last inspection.
FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 14 feet below the crown. Slide gate in a 36-inch corrugated metal pipe (CMP) riser on the waterside (WS) slope. Concrete distribution box on the landside (LS). (24-inch pipe [HLM 14.5] authorized under Automatic Board Order (ABO) issued as Permit No. 9508, 1974 - Jones). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 14.5)].
FS Date: 5/1/2017 10:34:48 AM

LM Start	14.50	Rating **	A/W	Issue No.	178 (cont)
LM End	14.50	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_51752_47361.jpg



Waterside view: levee mile marker

Photo 3 of 3 : UCIP_FA_2018_51752_47360.jpg



Landside view: overview of distribution box

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	16.30	Rating **	M	Issue No.	184
LM End	16.30	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.344177°	39.344177°
				-122.024300°	-122.024300°
DWR ID	17337				
Comment Code					
Inspector Comment					
FS_ID:51759 DS_ID:17337 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 4/20/2017 Abandoned- needs to be done so properly. (DWR Sutter Yard- AFreitag)11/1/2016 Abandoned. Pipe is buried and not visible but a white marker on WS shoulder shows its location. (DWR Sutter Yard- AFreitag)6/15/2016 Pipe was dug up and internally cleaned and camera inspected on 11/19/2015 by Nor-Cal Pipeline Services. Pipe section through the levee is 88ft long and showed signs of rusting but no holes or other deterioration was found. The WS flap gate was broken during excavation but doesnt pose an issue as the pipe was capped and reburied until further abandonment can be achieved. Unfortunately the pipe was not photographed when exposed.4/14/2016 Same as last inspection.4/2/2015 Unable to locate. Pipe has been selected to be dug up and internally camera inspected.7/2/2014 Unable to locate.12/19/2013 Unable to locate7/23/2013 Same as last inspection. Unable to locate. FIELD_STRUCT_DESC: 42-inch corrugated metal drainage pipe through the levee, 16.5 feet below the crown. Metal flap gate on the waterside (WS) silted over. Brick "U" shaped headwall on the WS toe. [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 16.29)]. FS Date: 5/1/2017 10:41:07 AM					

LM Start	16.30	Rating **	M	Issue No.	184 (cont)
LM End	16.30	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_51759_75096.jpg



View from crown down WS slope at location of crossing.

Photo 2 of 3 : UCIP_FA_2018_51759_75097.jpg



View of LS from crown at location of crossing.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	16.30	Rating **	M	Issue No.	184 (cont)
LM End	16.30	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.344177°	39.344177°
				-122.024300°	-122.024300°
DWR ID	17337				

Comment Code

Inspector Comment

FS_ID:51759
DS_ID:17337
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: 4/20/2017 Abandoned- needs to be done so properly. (DWR Sutter Yard- A Freitag)11/1/2016 Abandoned. Pipe is buried and not visible but a white marker on WS shoulder shows its location. (DWR Sutter Yard- A Freitag)6/15/2016 Pipe was dug up and internally cleaned and camera inspected on 11/19/2015 by Nor-Cal Pipeline Services. Pipe section through the levee is 88ft long and showed signs of rusting but no holes or other deterioration was found. The WS flap gate was broken during excavation but doesn't pose an issue as the pipe was capped and reburied until further abandonment can be achieved. Unfortunately the pipe was not photographed when exposed.4/14/2016 Same as last inspection.4/2/2015 Unable to locate. Pipe has been selected to be dug up and internally camera inspected.7/2/2014 Unable to locate.12/19/2013 Unable to locate.7/23/2013 Same as last inspection. Unable to locate.
FIELD_STRUCT_DESC: 42-inch corrugated metal drainage pipe through the levee, 16.5 feet below the crown. Metal flap gate on the waterside (WS) silted over. Brick "U" shaped headwall on the WS toe. [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 16.29)].
FS Date: 5/1/2017 10:41:07 AM

Photo 3 of 3 : UCIP_FA_2018_51759_75098.jpg



Looking up WS slope: bare spot where pipe was previously excavated, video inspected, and backfilled.

LM Start	16.43	Rating **	C	Issue No.	70
LM End	16.43	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.345695 °	39.345695 °
				-122.022820 °	-122.022820 °
DWR ID	DWR_ST0003_01 f _ 2016_70				

Comment Code

A1 : Exterminate rodents and backfill and compact or grout burrows.

Inspector Comment

The rodent holes were repaired along the landside slope.

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	17.58	Rating **	M	Issue No.	186
LM End	17.58	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		39.353531 °	39.353531 °	
			-122.009138 °	-122.009138 °	
DWR ID	17329				

Comment Code

Inspector Comment

FS_ID:51762
DS_ID:17329
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: 4/20/2017 Abandoned- needs to be done properly. Pipe had a small leak during high water and is believed to be caused by the screw gate not being fully closed before it was reburied after its internal inspection. (DWR Sutter Yard- AFreitag)11/1/2016
Abandoned. (DWR Sutter Yard- AFreitag)6/15/2016 Pipe was dug up and internally cleaned and camera inspected on 11/18/2015 by Nor-Cal Pipeline Services. Pipe section through levee is about 93.8ft long. Inspection showed signs of rusting but no holes or other deterioration was found. WS end and slidegate were photographed, LS end was not. After the inspection pipe ends were capped and reburied until further abandonment can be achieved.4/2/2015 WS pipe end was dug up in preparation for internal camera inspection. Only steel slide gate structure found on waterside.7/2/2014 Same as last inspection.12/19/2013 Same as last inspection.7/24/2013 Same as last inspection.
FIELD_STRUCT_DESC: *ABANDONED* 24-inch corrugated metal drainage pipe through the levee, 15.8 feet below the crown. Slide gate on the waterside (WS) end. Both pipe ends are silted over. [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 17.6)].
FS Date: 5/1/2017 10:45:36 AM

LM Start	17.58	Rating **	M	Issue No.	186 (cont)
LM End	17.58	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_51762_47384.jpg



Landside view: overview. No pipe found.

Photo 2 of 3 : UCIP_FA_2018_51762_47386.jpg



Waterside view: slide gate steel structure

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	17.58	Rating **	M	Issue No.	186 (cont)	
LM End	17.58	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.353531 °	39.353531 °	
				-122.009138 °	-122.009138 °	
DWR ID	17329					
Comment Code						
Inspector Comment						
FS_ID:51762 DS_ID:17329 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 4/20/2017 Abandoned- needs to be done properly. Pipe had a small leak during high water and is believed to be caused by the screw gate not being fully closed before it was reburied after its internal inspection. (DWR Sutter Yard- AFreitag)11/1/2016 Abandoned. (DWR Sutter Yard- AFreitag)6/15/2016 Pipe was dug up and internally cleaned and camera inspected on 11/18/2015 by Nor-Cal Pipeline Services. Pipe section through levee is about 93.8ft long. Inspection showed signs of rusting but no holes or other deterioration was found. WS end and slidegate were photographed, LS end was not. After the inspection pipe ends were capped and reburied until further abandonment can be achieved.4/2/2015 WS pipe end was dug up in preparation for internal camera inspection. Only steel slide gate structure found on waterside.7/2/2014 Same as last inspection.12/19/2013 Same as last inspection.7/24/2013 Same as last inspection. FIELD_STRUCT_DESC: *ABANDONED* 24-inch corrugated metal drainage pipe through the levee, 15.8 feet below the crown. Slide gate on the waterside (WS) end. Both pipe ends are silted over. [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 17.6)]. FS Date: 5/1/2017 10:45:36 AM						

Photo 3 of 3 : UCIP_FA_2018_51762_47385.jpg



Waterside view: buried slide gate

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	18.61	Rating **	A/W	Issue No.	191
LM End	18.61	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.362866 °	39.362866 °
				-121.997993 °	-121.997993 °
DWR ID	17345				

Comment Code

Inspector Comment

FS_ID:51770
DS_ID:17345
EP_NO: N/A
Repair Type: No Action Needed
Crossing Status: Found
UCIP Comments: 4/20/2017 Crossing appears to be in good condition. (DWR Sutter Yard- AFreitag)11/1/2016 Crossing appears to be in good condition. (DWR Sutter Yard- AFreitag)6/16/2016 Pipe was internally cleaned and camera inspected on 11/19/2015 by Nor-Cal Pipeline Services. Pipe is 155ft in total length and the inspection showed some minor rusting but no holes or other deformations were found. Pipe is still used by the landowner for irrigation and the sloughing near the WS end was repaired and rocked to prevent future sloughing or erosion.4/14/2016 Sloughing repaired by Sutter Yard with rock revetment.4/2/2015 Same as last inspection. Pipe has been selected for internal camera inspection.Sloughing at outlet and levee slope is damaged due to sloughing.7/2/2014 It is not an abandoned crossing. Sloughing at outlet and levee slope is damaged due to sloughing.12/19/2013 Same as last inspection.7/24/2013 Same as last inspection.
FIELD_STRUCT_DESC: 36-inch corrugated metal drainage pipe through the levee, 20 feet below the crown. Slide gate at the waterside (WS) toe. [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 18.65)].
FS Date: 5/1/2017 10:52:46 AM

LM Start	18.61	Rating **	A/W	Issue No.	191 (cont)
LM End	18.61	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_51770_47399.jpg



Waterside view: overview of sliding gate structure

Photo 2 of 3 : UCIP_FA_2018_51770_47398.jpg



Waterside view: outlet pipe with concrete headwall and floor apron.

* Location	** Rating	+ Issue Type
LS : Land Side WS : Water Side CR : Crown	A : Acceptable M : Minimally Acceptable U : Unacceptable	Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
N/A : Not Applicable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	18.61	Rating **	A/W	Issue No.	191 (cont)	
LM End	18.61	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.362866 °	39.362866 °	
				-121.997993 °	-121.997993 °	
DWR ID	17345					
Comment Code						
Inspector Comment						
FS_ID:51770 DS_ID:17345 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 4/20/2017 Crossing appears to be in good condition. (DWR Sutter Yard- A Freitag)11/1/2016 Crossing appears to be in good condition. (DWR Sutter Yard- A Freitag)6/16/2016 Pipe was internally cleaned and camera inspected on 11/19/2015 by Nor-Cal Pipeline Services. Pipe is 155ft in total length and the inspection showed some minor rusting but no holes or other deformations were found. Pipe is still used by the landowner for irrigation and the sloughing near the WS end was repaired and rocked to prevent future sloughing or erosion.4/14/2016 Sloughing repaired by Sutter Yard with rock revetment.4/2/2015 Same as last inspection. Pipe has been selected for internal camera inspection.Sloughing at outlet and levee slope is damaged due to sloughing.7/2/2014 It is not an abandoned crossing. Sloughing at outlet and levee slope is damaged due to sloughing.12/19/2013 Same as last inspection.7/24/2013 Same as last inspection. FIELD_STRUCT_DESC: 36-inch corrugated metal drainage pipe through the levee, 20 feet below the crown. Slide gate at the waterside (WS) toe. [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 18.65)]. FS Date: 5/1/2017 10:52:46 AM						

Photo 3 of 3 : UCIP_FA_2018_51770_47403.jpg



Waterside view: sloughing at outlet pipe

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	18.70	Rating **	A/W	Issue No.	192
LM End	18.70	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.364067 °	39.364067 °
				-121.997792 °	-121.997792 °
DWR ID	17346				

Comment Code

Inspector Comment

FS_ID:51771
DS_ID:17346
EP_NO: 9503
Repair Type: No Action Needed
Crossing Status: Found
UCIP Comments: 4/20/2017 Crossing appears to be in good condition.
(DWR Sutter Yard- A Freitag)11/1/2016 Crossing appears to be in good condition. (DWR Sutter Yard- A Freitag)6/16/2016 Pipe was internally cleaned and camera inspected on 11/19/2015 by Nor-Cal Pipeline Services. 129.5 ft (starting from the WS end) was inspected to get get us through the levee prism but the LS end was never found. Pipe showed no signs of rust or damage.4/14/2016 Inlet structure still filled with soil.4/2/2015 Same as last inspection. Pipe has been selected for internal camera inspection.According to local people, the crossing is functional. The gap between 8-inch and 24-inch pipes is grouted with cement. Inlet structure is filled with soil.7/2/2014 Same as last inspection.12/19/2013 Same as last inspection.7/24/2013 Same as last inspection.
FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 19 feet below the crown. 8-inch steel pipe sleeved through the 24-inch pipe. Annular space cement grouted. Slide gate at the waterside (WS) toe. Concrete inlet box on the landside (LS). (24-inch pipe [HLM 18.74] authorized under Automatic Board Order (ABO) issued as Permit No. 9503, 1974 - Baird). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 18.74)].
FS Date: 5/1/2017 10:53:44 AM

LM Start	18.70	Rating **	A/W	Issue No.	192 (cont)
LM End	18.70	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_51771_47442.jpg



Waterside view: overview of slide gate structure

Photo 2 of 3 : UCIP_FA_2018_51771_47441.jpg



Waterside view: 8-inch pipe inside 24-inch CMP

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	18.70	Rating **	A/W	Issue No.	192 (cont)
LM End	18.70	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.364067 °	39.364067 °
				-121.997792 °	-121.997792 °
DWR ID	17346				

Comment Code

Inspector Comment

FS_ID:51771
DS_ID:17346
EP_NO: 9503
Repair Type: No Action Needed
Crossing Status: Found
UCIP Comments: 4/20/2017 Crossing appears to be in good condition.
(DWR Sutter Yard- A Freitag)11/1/2016 Crossing appears to be in good condition. (DWR Sutter Yard- A Freitag)6/16/2016 Pipe was internally cleaned and camera inspected on 11/19/2015 by Nor-Cal Pipeline Services. 129.5 ft (starting from the WS end) was inspected to get us through the levee prism but the LS end was never found. Pipe showed no signs of rust or damage.4/14/2016 Inlet structure still filled with soil.4/2/2015 Same as last inspection. Pipe has been selected for internal camera inspection.According to local people, the crossing is functional. The gap between 8-inch and 24-inch pipes is grouted with cement. Inlet structure is filled with soil.7/2/2014 Same as last inspection.12/19/2013 Same as last inspection.7/24/2013 Same as last inspection.
FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 19 feet below the crown. 8-inch steel pipe sleeved through the 24-inch pipe. Annular space cement grouted. Slide gate at the waterside (WS) toe. Concrete inlet box on the landside (LS). (24-inch pipe [HLM 18.74] authorized under Automatic Board Order (ABO) issued as Permit No. 9503, 1974 - Baird). [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 18.74)].
FS Date: 5/1/2017 10:53:44 AM

Photo 3 of 3 : UCIP_FA_2018_51771_47440.jpg



Waterside view: 8-inch pipe and drain gate

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	19.19	Rating **	A/W	Issue No.	193
LM End	19.19	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.370031 °	39.370031 °
				-121.996458 °	-121.996458 °
DWR ID	17347				
Comment Code					
Inspector Comment					
FS_ID:51773 DS_ID:17347 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 4/20/2017 Abandoned- plugged. (DWR Sutter Yard-AFreitag)11/1/2016 Abandoned/plugged. (DWR Sutter Yard-AFreitag)6/16/2016 Internal camera inspection was done on 11/19/2015 by Nor-Cal Pipeline Servies. Pipe was inspected starting from the WS end and inspected upto the grout plug that is 13.7ft into the pipe. Pipe was then capped and reburied until further abandonment can be achieved.4/2/2015 WS end of pipe was dug up in preparation for internal camera inspection. Only steel slide gate structure found on WS.7/2/2014 Same as last inspection.12/19/2013 Same as last inspection.7/24/2013 Same as last inspection. FIELD_STRUCT_DESC: *ABANDONED* 36-inch corrugated metal drainage pipe through the levee, 21.7 feet below the crown. Slide gate at the waterside (WS) toe. Pipe grouted on the WS end. [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 19.24)]. FS Date: 5/1/2017 10:55:06 AM					

LM Start	19.19	Rating **	A/W	Issue No.	193 (cont)
LM End	19.19	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_51773_47447.jpg



Waterside view: overview of abandoned slide gate structure

Photo 2 of 3 : UCIP_FA_2018_51773_47446.jpg



Landside view: overview (no pipes)

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	19.19	Rating **	A/W	Issue No.	193 (cont)	
LM End	19.19	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.370031 °	39.370031 °	
				-121.996458 °	-121.996458 °	
DWR ID	17347					
Comment Code						
Inspector Comment						
FS_ID:51773 DS_ID:17347 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: 4/20/2017 Abandoned- plugged. (DWR Sutter Yard-AFreitag)11/1/2016 Abandoned/plugged. (DWR Sutter Yard-AFreitag)6/16/2016 Internal camera inspection was done on 11/19/2015 by Nor-Cal Pipeline Servies. Pipe was inspected starting from the WS end and inspected upto the grout plug that is 13.7ft into the pipe. Pipe was then capped and reburied until further abandonment can be achieved.4/2/2015 WS end of pipe was dug up in preparation for internal camera inspection. Only steel slide gate structure found on WS.7/2/2014 Same as last inspection.12/19/2013 Same as last inspection.7/24/2013 Same as last inspection. FIELD_STRUCT_DESC: *ABANDONED* 36-inch corrugated metal drainage pipe through the levee, 21.7 feet below the crown. Slide gate at the waterside (WS) toe. Pipe grouted on the WS end. [Additional Reference(s): DWR Levee Log, 2002. USACE Sacramento O&M Manual 136, March 1960 (HLM 19.24)]. FS Date: 5/1/2017 10:55:06 AM						

Photo 3 of 3 : UCIP_FA_2018_51773_73781.jpg



WS pipe end and screw gate

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	19.55	Rating **	M	Issue No.	194
LM End	19.55	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.375221 °	39.375221 °
				-121.995878 °	-121.995878 °
DWR ID	17487				
Comment Code					
Inspector Comment					
FS_ID:51775					
DS_ID:17487					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: 4/20/2017 Abandoned- needs to be done so properly. (DWR Sutter Yard- A Freitag)11/1/2016 Abandoned.(DWR Sutter Yard- A Freitag)6/3/2016 Abandoned crossing.4/2/2015 Same as last inspection. Slide Gate WS not found. An abandoned pump and steel pipe found on WS. A 6 ft x 8 ft concrete distribution box with a CMP found on LS. Box filled with soil. An abandoned crossing.7/2/2014 Same as last inspection.12/19/2013 Same as last inspection.7/24/2013 Same as last inspection.					
FIELD_STRUCT_DESC: *ABANDONED* 36-inch corrugated metal drainage pipe through the levee, invert 21.7 feet below the crown.					
Abandoned pump and steel pipe found on the waterside (WS). 6 foot by 8 foot concrete distribution box with the 36-inch corrugated metal pipe found on the landside (LS). [Additional Reference(s): USACE Sacramento O&M Manual 136, March 1960 (HLM 19.61)].					
FS Date: 5/1/2017 10:56:50 AM					

Photo 1 of 3 : UCIP_FA_2018_51775_47449.jpg



Waterside view: overview

LM Start	19.55	Rating **	M	Issue No.	194 (cont)
LM End	19.55	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_51775_47448.jpg



Waterside view: abandoned and ruined pipe

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	19.85	10/10/2018 10/10/2018	Bob Duffey

LM Start	19.55	Rating **	M	Issue No.	194 (cont)	
LM End	19.55	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.375221°	39.375221°	
				-121.995878°	-121.995878°	
DWR ID	17487					
Comment Code						
Inspector Comment						
FS_ID:51775						
DS_ID:17487						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: 4/20/2017 Abandoned- needs to be done so properly. (DWR Sutter Yard- A Freitag)11/1/2016 Abandoned.(DWR Sutter Yard- A Freitag)6/3/2016 Abandoned crossing.4/2/2015 Same as last inspection. Slide Gate WS not found. An abandoned pump and steel pipe found on WS. A 6 ft x 8 ft concrete distribution box with a CMP found on LS. Box filled with soil. An abandoned crossing.7/2/2014 Same as last inspection.12/19/2013 Same as last inspection.7/24/2013 Same as last inspection.						
FIELD_STRUCT_DESC: *ABANDONED* 36-inch corrugated metal drainage pipe through the levee, invert 21.7 feet below the crown.						
Abandoned pump and steel pipe found on the waterside (WS). 6 foot by 8 foot concrete distribution box with the 36-inch corrugated metal pipe found on the landside (LS). [Additional Reference(s): USACE Sacramento O&M Manual 136, March 1960 (HLM 19.61)].						
FS Date: 5/1/2017 10:56:50 AM						

Photo 3 of 3 : UCIP_FA_2018_51775_47453.jpg



Waterside view: abandoned and ruined pipe

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Colusa Bypass	Right	2.20	10/25/2018 10/25/2018	Bob Duffey

LM Start	0.02	Rating **	M	Issue No.	1
LM End	0.02	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.232058 °	39.232058 °
				-121.995514 °	-121.995514 °
DWR ID	DWR_ST0003_02_s_2012_1				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

LM Start	0.37	Rating **	A	Issue No.	3
LM End	0.37	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.231415 °	39.231415 °
				-121.989060 °	-121.989060 °
DWR ID	DWR_ST0003_02_f_2018_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The vegetation was burned off of both slopes.					

Photo 1 of 1 : FA_2018_ST0003_265_3_20181102_00004.jpg



View of no vegetation on both slopes.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Colusa Bypass	Left	2.29	10/25/2018 10/25/2018	Bob Duffey

LM Start	0.67	Rating **	A	Issue No.	1
LM End	0.67	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.237682 °	39.237682 °
				-121.981938 °	-121.981938 °
DWR ID	DWR_ST0003_03_f_2018_1				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The vegetation was burned off of both slopes.					

Photo 1 of 1 : FA_2018_ST0003_266_1_20181102_00002.jpg



View of no vegetation on both slopes.

LM Start	1.94	Rating **	M	Issue No.	10
LM End	1.94	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.244888 °	39.244888 °
				-121.965595 °	-121.965595 °
DWR ID	DWR_ST0003_03_s_2012_10				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

LM Start	2.13	Rating **	M	Issue No.	2
LM End	2.13	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.244925 °	39.244925 °
				-121.962072 °	-121.962072 °
DWR ID	DWR_ST0003_03_s_2015_2				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Moulton Bypass	Right	0.30	10/10/2018 10/10/2018	Bob Duffey

LM Start	0.10	Rating **	A	Issue No.	1
LM End	0.10	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.337763 °	39.337763 °
				-122.020342 °	-122.020342 °
DWR ID	DWR_ST0003_04_f_2018_1				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The vegetation has been removed from both slopes.					

Photo 1 of 1 : FA_2018_ST0003_267_1_20181105_00001.jpg



View of no vegetation on both slopes.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard East Levee Sacramento River

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Moulton Bypass	Left	2.19	10/10/2018 10/10/2018	Bob Duffey

LM Start	0.35	Rating **	A	Issue No.	2
LM End	0.35	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.343242°	39.343242°
				-122.016578°	-122.016578°
DWR ID	DWR_ST0003_05_f_2018_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The vegetation has been removed from both slopes.					

Photo 1 of 1 : FA_2018_ST0003_268_2_20181105_00003.jpg



View of no vegetation on both slopes.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---